


RESIN



MINI PROJECT BROCHURE

ABOUT US



For over twenty years, DC Flooring has redefined industry standards, emerging as the go-to supplier and installer of premium-quality flooring across the U.K. and beyond. Rooted in a customer-centric ethos and fuelled by unparalleled craftsmanship, our journey is characterised by a relentless pursuit of excellence.

ART GALLERY - LONDON



Location: West London

Sector: Arts and Culture

Timeline: One week

Summary: Removed loose screed and repaired the substrate, reinforcing cracks within the concrete slab. A water-based mid-grey epoxy coating was then applied, delivering a smooth, durable finish with improved structural integrity.



MOLTON BROWN

Location: Bishopstortford



Sector: Commercial / Manufacturing (luxury fragrance & beauty)

Client: Molton Brown

Scope: Diamond grinding of existing concrete floor. Self-leveling epoxy flooring system & coving

Timeline: Delivered on time and within budget

Summary: Installed a high-performance epoxy floor capable of withstanding heavy use, chemical exposure, and frequent cleaning. Despite multiple trades on site, careful planning ensured smooth delivery. The project was completed on time, within budget, and finished with a durable, seamless floor.





BOYN VALLEY WAREHOUSE - READING




Location: Reading

Sector: Refurbishment of Warehouse

Timeline: 10 days

Summary: Existing epoxy SL was removed using aggressive PCD diamond grinding. Localised concrete repairs were carried out to remediate the slab before full regrinding. The floor was then recoated with Flowercrete SF41. Expansion joints were saw-cut and resealed using a suitable jointing mastic to complete the system







ARCHES - LONDON

HODDESON POWER STATION






Location: Hoddeson

Sector: Industrial

Timeline: 4 days

Summary: Ground the existing floor to remove the failing resin coating and expose a smooth concrete slab. Applied two coats of high-build epoxy, reinstated joints, and installed yellow line marking, delivering a durable, compliant finish suitable for a power station environment.





DAB GROUP - IPSWICH



Location: Ipswich

Sector: Industrial

Timeline: 3 days to remove the line marking - 9 in total

Summary: Removed existing line markings, ground back exposed aggregate, and applied epoxy scratch coats where required. Installed a two-pack deep-fill filler, diamond-sanded for a smooth finish, then applied a high-build epoxy topcoat for a durable, seamless result.







WAREHOUSE IN SOUTHAMPTON



UNIT D WAREHOUSE - HODDESON



LINE MARKING IN FORDS DUNTON



Location: Fords Laindon

Sector: Automotive Industry

Client: Ford

Timeline: One week

Summary: Removed the flaky existing coating and prepared the substrate before applying a new durable system. Reinstated clear, compliant line marking to create a safe, well-defined work area around new machinery.

BOREHAM BIKE CLUB



Location: Chelmsford



Sector: Automotive | Commercial

Client: Boreham Motorbike Centre

Scope: Floor repairs, anti-slip treatment,
and line-marked bays

Timeline: Completed with only one extra
day added despite challenges

Summary: Refreshed and repaired the
centre's flooring, fixing blown screed and
sealing cracks with epoxy, added anti-slip
resin and line-marked bays. Despite
unexpected substrate issues, careful
planning kept the job on track and
delivered a flat, durable, and attractive
floor.





PROLOGIS CHESSINGTON



Let us bring your vision to life.



www.deflooring.co.uk | info@deflooring.co.uk